

FO0E80" 02241650




FIG. 1b
PRIOR ART


[illegible]

FIG. 2
PRIOR ART




FIG. 3a
PRIOR ART




FIG. 3b
PRIOR ART





FIG. 4a




FIG. 4b




FIG. 5




FIG. 6










FIG. 7c



100E80 02241660

T00E80" 02244660



Sect. D-D FIG. 8a

FIG. 9a

FIG. 9a




FIG. 9b






FIG. 10



Section B-B in FIG. 10






FIG. 11

TOPPED 02244660

FIG. 12



Section B-B in FIG. 10




FIG. 13





FIG. 14

FIG. 15




FIG. 16




FIG. 17




FIG. 18

FIG. 18





FIG. 19







FIG. 20

FIG. 21

FIG. 21







FIG. 22



0944220 0001



FOUOESD-02244660




FIG. 25






FIG 26




[illegible]

FIG. 27

